




LOCHER
Learning Occupational Health
by Experiencing Risks



Poster design: CLARK DIXON, JORDAN
CLAYDEN, JOE COLLIER, LUKE KNIGHT &
THOMAS EVANS

WELDING and CUTTING FUME CAN AFFECT YOUR HEALTH

Always Control Your Exposure

Examples of control measures



Reduce arcing time




Use on-tool extraction



Keep head outside the plume



Use extraction. Keep weld area within the capture bubble.



Minimise work in restricted and confined spaces



Use turntable, if you can



Maximise the use of natural air movement and ventilated spaces



Select the right RPE and use it correctly, where necessary

