



You only have one set of lungs and only one life!



Exposure to Welding fume can lead to

- **Asthma**
- **Lung disease**
- **Pneumonia**
- **Cancer**

You can prevent

- ✓ **Use the right techniques, LEV, on-tool extraction and RPE, as necessary**
- ✓ **Always Keep the head outside the plume**
- ✓ **Avoid welding in congested spaces, greasy and painted surfaces**

